

FIRE TEST FOR SOFT-SEATED FLANGED BALL VALVE

J.C. FABRICA DE VALVULAS, S.A.

BCL 9800596/4 Certificate Number.

Office.

BARCELONA

Client's Order Number.

15.06.98 Date.

Order Status

complete

Inspection Dates

First: 15.05.98 15.05.98

This certificate is issued to Messrs. J.C. FABRICA DE VALVULAS, S.A. upon their request that the undersigned Surveyor to this Society did attend their works at Rubi - Barcelona (Spain) for the purpose of witnessing the FIRE TEST in accordance with the requirements specified in API 607-1993 on the following type of valve:

A manually operated soft seated flanged ball valve of 1/2" reduced bore, bi-directional as per

Fig. 715 A.I.T. DN 1/2", ANSI 150# RF,RB

Body material: A-216- WCB

Seats: PTFE

Ball material: A-351 CF8M

Manufacturers identifying numbers: BODY: 715151

Body connector: -----

Mass: 1,6 Kgs

Marks:

**BODY** 

NYB

**BODY CONNECTOR** 

ID

The test conducted on the valve previously subject to hydraulic pressure was as follows:

The valve, filled with water under test pressure, was put in a box and exposed to flames with and environmental temperature between 760 - 980°C. All measure temperatures shall be above 705°C. The body temperature shall be at 593° C minimun and bonnet temperature of 650°C minimum for a period of during 30 minutes and established the leakage through the seat and external to atmosphere during this period. The temperature was checked and recorded every each thirty seconds, while leakages were determined using containers collecting the water leaked during burn period. Afterwards water spray so that it is rapidly cooled to below 100°C within ten minutes. Internal leakage measure during cooling time. Following operational test. Subsequently manual opened up and closed to under test pressure differential and finally the valve was hidrotested during five minutes and during this period internal and external leakage were measured.



Certificate Number: BCL 9800596/4

Office: BARCELONA
Date: 15.06.98
Page: 2 of 2

All the following values were determined and recorded together with temperatures, times and pressures as shown on manufacturers Fire Safe Test Report no. API 607-715/1/2"

- 1.-Internal leakage during burning test Satisfactory
- 2.-External leakage during burning and cooling test Satisfactory
- 3.-Operatibility to full open position test Satisfactory
- 4.-Internal and External leakage during after operational test Satisfactory

The valve was subject to a visual examination with satisfactory results and subsequently dismantled in order to verify that valves components comply with the drawing and parts list supplied by the manufacturer, while seat rings were found partially destroyed.

The manufacturers Fire Safe Test Report no. API 607-715/½" and drawing 2272/715AIT15 herewith attached were satisfactory checked and signed.

The above is considered in accordance with the mentioned specifications requirements, therefore the subject valve has satisfactorily passed the prescribed fire test and can be also qualified as follows:

NPS

CLASS RATING

MATERIALS

1/4", 3/8", 1/2", 3/4"


150# and 300#

Carbon steel, (see drawing)

J.Gil for P. Picazo

Surveyors to Lloyd's Register

**DOCUMENTS ATTACHED:** 





Project: FIRE TEST FOR SOFT-SEATED

FLANGED BALL VALVE

Client: J.C. FABRICA DE VALVULAS, S.A.

Certificate Number: BCL 9800596/3

Office BARCELONA

Client's Order Number. ----

Date: 15.06.98

Order Status: complete

Inspection Dates

First: 15.05.98

Final: 15.05.98

This certificate is issued to Messrs. J.C. FABRICA DE VALVULAS, S.A. upon their request that the undersigned Surveyor to this Society did attend their works at Rubi - Barcelona (Spain) for the purpose of witnessing the FIRE TEST in accordance with the requirements specified in API 607-1993 on the following type of valve:

A manually operated soft seated flanged ball valve of 1" reduced bore, bi-directional as per

Fig. 715 A.I.T. DN 1", ANSI 150# RF,RB

Body material: A-216- WCB

Seats: PTFE

Ball material: A-351 CF8M

Manufacturers identifying numbers: BODY: 715251

Body connector: -----

Mass: 2,7 Kgs

Marks:

BODY

NZR

**BODY CONNECTOR** 

IP

The test conducted on the valve previously subject to hydraulic pressure was as follows:

The valve, filled with water under test pressure, was put in a box and exposed to flames with and environmental temperature between 760 - 980°C. All measure temperatures shall be above 705°C. The body temperature shall be at 593° C minimum and bonnet temperature of 650°C minimum for a period of during 30 minutes and established the leakage through the seat and external to atmosphere during this period. The temperature was checked and recorded every each thirty seconds, while leakages were determined using containers collecting the water leaked during burn period. Afterwards water spray so that it is rapidly cooled to below 100°C within ten minutes. Internal leakage measure during cooling time. Following operational test. Subsequently manual opened up and closed to under test pressure differential and finally the valve was hidrotested during five minutes and during this period internal and external leakage were measured.

../ ..

A.



Certificate Number: BCL 9800596/3

Office: BARCELONA
Date: 15.06.98
Page: 2 of 2

All the following values were determined and recorded together with temperatures, times and pressures as shown on manufacturers Fire Safe Test Report no. API 607-715/1"

- 1.-Internal leakage during burning test Satisfactory
- 2.-External leakage during burning and cooling test Satisfactory
- 3.-Operatibility to full open position test Satisfactory
- 4.-Internal and External leakage during after operational test Satisfactory

The valve was subject to a visual examination with satisfactory results and subsequently dismantled in order to verify that valves components comply with the drawing and parts list supplied by the manufacturer, while seat rings were found partially destroyed.

The manufacturers Fire Safe Test Report no. API 607-715/1" and drawing 2271/715AIT25 herewith attached were satisfactory checked and signed.

The above is considered in accordance with the mentioned specifications requirements, therefore the subject valve has satisfactorily passed the prescribed fire test and can be also qualified as follows:

**NPS** 

CLASS RATING

**MATERIALS** 


1/2", 1", 11/4", 11/2"

150# and 300#

Carbon steel, (see drawing)

J.Gif for P. Picazo
Surveyors to Lloyd's Register

DOCUMENTS ATTACHED:





Project: FIRE TEST FOR SOFT-SEATED

FLANGED BALL VALVE

J.C. FABRICA DE VALVULAS, S.A.

Office BARCELONA

BCL 9800547/3

Client's Order Number. -

Date: 22.05.98

Order Status complete

Certificate Number.

Inspection Dates

First: 17.04.98

Final: 17.04.98

This certificate is issued to Messrs. J.C. FABRICA DE VALVULAS, S.A. upon their request that the undersigned Surveyor to this Society did attend their works at Rubi - Barcelona (Spain) for the purpose of witnessing the FIRE TEST in accordance with the requirements specified in API 607-1993 on the following type of valve:

A manually operated soft seated flanged ball valve of 2" reduced bore, bi-directional as per

Fig. 715 A.I.T. DN 2", ANSI 150# RF,RB

Body material: A-216- WCB

Seats: PTFE

Ball material: A-351 CF8M

Manufacturers identifying numbers: BODY: 715501

Body connector: 7150020

Mass: 7,9 Kgs

Marks:

BODY

M45

**BODY CONNECTOR** 

E

The test conducted on the valve previously subject to hydraulic pressure was as follows:

The valve, filled with water under test pressure, was put in a box and exposed to flames with and environmental temperature between 760 - 980°C. All measure temperatures shall be above 705°C. The body temperature shall be at 593° C minimum and bonnet temperature of 650°C minimum for a period of during 30 minutes and established the leakage through the seat and external to atmosphere during this period. The temperature was checked and recorded every each thirty seconds, while leakages were determined using containers collecting the water leaked during burn period. Afterwards water spray so that it is rapidly cooled to below 100°C within ten minutes. Internal leakage measure during cooling time. Following operational test. Subsequently manual opened up and closed to under test pressure differential and finally the valve was hidrotested during five minutes and during this period internal and external leakage were measured.

../..



Certificate Number: BCL 9800547/3
Office: BARCELONA

Date: 22.05.98 Page: 2 of 2

All the following values were determined and recorded together with temperatures, times and pressures as shown on manufacturers Fire Safe Test Report no. API 607-715/2"

- 1.-Internal leakage during burning test Satisfactory
- 2.-External leakage during burning and cooling test Satisfactory
- 3.-Operatibility to full open position test Satisfactory
- 4.-Internal and External leakage during after operational test Satisfactory

The valve was subject to a visual examination with satisfactory results and subsequently dismantled in order to verify that valves components comply with the drawing and parts list supplied by the manufacturer, while seat rings were found partially destroyed.

The manufacturers Fire Safe Test Report no. API 607-715/2" and drawing 2234/715AIT50L herewith attached were satisfactory checked and signed.

The above is considered in accordance with the mentioned specifications requirements, therefore the subject valve has satisfactorily passed the prescribed fire test and can be also qualified as follows:

**NPS** 

**CLASS RATING** 

MATERIALS


11/2, 2, 21/2, and 3"

150# and 300#

Carbon steel, (see drawing)

J.Gil for P. Picazo
Surveyors to Lloyd's Register

**DOCUMENTS ATTACHED:** 





FIRE TEST FOR SOFT-SEATED

FLANGED BALL VALVE

Climb J.C. PABRICA DE VALVULAS, S.A.

Client's Order Number

Inspection Dates

First: 07.05.98

BCL 9800547/4 Certificate Number.

BARCELONA

Date 22.05.98

complete

Order Status

This certificate is issued to Messrs. J.C. FABRICA DE VALVULAS, S.A. upon their request that the undersigned Surveyor to this Society did attend their works at Rubi - Barcelona (Spain) for the purpose of witnessing the FIRE TEST in accordance with the requirements specified in API 607-1993 on the following type of valve:

A manually operated soft seated flanged ball valve of 4" reduced bore, bi-directional as per

Fig. 715 A.I.T. DN 4", ANSI 150# RF, RB

Body material: A-216- WCB

Seats: PTFE

Ball material: A-351 CF8M

Manufacturers identifying numbers: BODY: 715811

Body connector: 7181020B

Mass: 30 Kgs

Marks:

BODY **BODY CONNECTOR**  038

The test conducted on the valve previously subject to hydraulic pressure was as follows:

The valve, filled with water under test pressure, was put in a box and exposed to flames with and environmental temperature between 760 - 980°C. All measure temperatures shall be above 705°C. The body temperature shall be at 593° C minimun and bonnet temperature of 650°C minimum for a period of during 30 minutes and established the leakage through the seat and external to atmosphere during this period. The temperature was checked and recorded every each thirty seconds, while leakages were determined using containers collecting the water leaked during burn period. Afterwards water spray so that it is rapidly cooled to below 100°C within ten minutes. Internal leakage measure during cooling time. Following operational test. Subsequently manual opened up and closed to under test pressure differential and finally the valve was hidrotested during five minutes and during this period internal and external leakage were measured.



Certificate Number: BCL 9800547/4

Office BARCELONA
Date 22.05.98
Page 2 of 2

All the following values were determined and recorded together with temperatures, times and pressures as shown on manufacturers Fire Safe Test Report no. API 607-715/4"

- 1.-Internal leakage during burning test Satisfactory
- 2.-External leakage during burning and cooling test Satisfactory
- 3.-Operatibility to full open position test Satisfactory
- 4.-Internal and External leakage during after operational test Satisfactory

The valve was subject to a visual examination with satisfactory results and subsequently dismantled in order to verify that valves components comply with the drawing and parts list supplied by the manufacturer, while seat rings were found partially destroyed.

The manufacturers Fire Safe Test Report no. API 607-715/4" and drawing 2244/715AIT100 herewith attached were satisfactory checked and signed.

The above is considered in accordance with the mentioned specifications requirements, therefore the subject valve has satisfactorily passed the prescribed fire test and can be also qualified as follows:

**NPS** 

**CLASS RATING** 

**MATERIALS** 

3", 4", 5", and 6"


150# and 300#

Carbon steel, (see drawing)

Gil for P. Picazo

DOCUMENTS ATTACHED:

Surveyors to Lloyd's Register





Project: FIRE TEST FOR SOFT-SEATED

FLANGED BALL VALVE

Certificate Number: BCL 9800603/3

Client: J.C. FABRICA DE VALVULAS, S.A.

Office: BARCELONA

Client's Order Number: --

Date: 30.06.98

Order Status: complete

Inspection Dates

First: 09.06.98

Final: 09.06.98

This certificate is issued to Messrs. J.C. FABRICA DE VALVULAS, S.A. upon their request that the undersigned Surveyor to this Society did attend their works at Rubi - Barcelona (Spain) for the purpose of witnessing the FIRE TEST in accordance with the requirements specified in API 607-1993 on the following type of valve:

A manually operated soft seated flanged ball valve of 8" full bore, bi-directional as per

Fig. 515 A.I.T. DN 8", ANSI 150# RF,FB

Body material: A-216- WCB

Seats: PTFE

Ball material: A-351 CF8M

Manufacturers identifying numbers: BODY: 5102001

Body connector: 5102002

Mass: 167 Kgs

Marks:

BODY

M-30

**BODY CONNECTOR** 

M-31

The test conducted on the valve previously subject to hydraulic pressure was as follows:

The valve, filled with water under test pressure, was put in a box and exposed to flames with and environmental temperature between 760 - 980°C. All measure temperatures shall be above 705°C. The body temperature shall be at 593° C minimun and bonnet temperature of 650°C minimum for a period of during 30 minutes and established the leakage through the seat and external to atmosphere during this period. The temperature was checked and recorded every each thirty seconds, while leakages were determined using containers collecting the water leaked during burn period. Afterwards water spray so that it is rapidly cooled to below 100°C within ten minutes. Internal leakage measure during cooling time. Following operational test. Subsequently manual opened up and closed to under test pressure differential and finally the valve was hidrotested during five minutes and during this period internal and external leakage were measured.

../..



Certificate Number: BCL 9800603/3

Office: BARCELONA

Date: 30.06.98

Page: 2 of 2

All the following values were determined and recorded together with temperatures, times and pressures as shown on manufacturers Fire Safe Test Report no. API 607-515/8"

- 1.-Internal leakage during burning test Satisfactory
- 2.-External leakage during burning and cooling test Satisfactory
- 3.-Operatibility to full open position test Satisfactory
- 4.-Internal and External leakage during after operational test Satisfactory

The valve was subject to a visual examination with satisfactory results and subsequently dismantled in order to verify that valves components comply with the drawing and parts list supplied by the manufacturer, while seat rings were found partially destroyed.

The manufacturers Fire Safe Test Report no. API 607-515/8" and drawing 2380/515NAI1T200RA herewith attached were satisfactory checked and signed.

The above is considered in accordance with the mentioned specifications requirements, therefore the subject valve has satisfactorily passed the prescribed fire test and can be also qualified as follows:

NPS

**CLASS RATING** 

**MATERIALS** 

6" and larger


150# and 300#

Carbon steel, (see drawing)

J.Gil for P. Picazo

Surveyors to Lloyd's Register

**DOCUMENTS ATTACHED:** 





FIRE TEST FOR SOFT-SEATED Project:

FLANGED BALL VALVE

BCL 9800603/1 Certificate Number.

J.C. FABRICA DE VALVULAS, S.A.

BARCELONA Office.

Client's Order Number

30.06.98 Date

Order Status:

complete

Inspection Dates

26.05.98 First.

26.05.98

This certificate is issued to Messrs. J.C. FABRICA DE VALVULAS, S.A. upon their request that the undersigned Surveyor to this Society did attend their works at Rubi - Barcelona (Spain) for the purpose of witnessing the FIRE TEST in accordance with the requirements specified in API 607-1993 on the following type of valve:

A manually operated soft seated flanged ball valve of 8" reduced bore, bi-directional as per

Fig. 715 A.I.T. DN 8", ANSI 150# RF,RB

Body material: A-216- WCB

Seats: PTFE

Ball material: A-351 CF8M

Manufacturers identifying numbers: BODY: 715841

Body connector: Mass: 77 Kgs Marks:

**BODY** 

M05

**BODY CONNECTOR** 

The test conducted on the valve previously subject to hydraulic pressure was as follows:

The valve, filled with water under test pressure, was put in a box and exposed to flames with and environmental temperature between 760 - 980°C. All measure temperatures shall be above 705°C. The body temperature shall be at 593° C minimum and bonnet temperature of 650°C minimum for a period of during 30 minutes and established the leakage through the seat and external to atmosphere during this period. The temperature was checked and recorded every each thirty seconds, while leakages were determined using containers collecting the water leaked during burn period. Afterwards water spray so that it is rapidly cooled to below 100°C within ten minutes. Internal leakage measure during cooling time. Following operational test. Subsequently manual opened up and closed to under test pressure differential and finally the valve was hidrotested during five minutes and during this period internal and external leakage were measured.

../..



Certificate Number: BCL 9800603/1

Office BARCELONA
Date 30.06.98
Page 2 of 2

All the following values were determined and recorded together with temperatures, times and pressures as shown on manufacturers Fire Safe Test Report no. API 607-715/8"

- 1.-Internal leakage during burning test Satisfactory
- 2.-External leakage during burning and cooling test Satisfactory
- 3.-Operatibility to full open position test Satisfactory
- 4.-Internal and External leakage during after operational test Satisfactory

The valve was subject to a visual examination with satisfactory results and subsequently dismantled in order to verify that valves components comply with the drawing and parts list supplied by the manufacturer, while seat rings were found partially destroyed.

The manufacturers Fire Safe Test Report no. API 607-715/8" and drawing 2333/715AIT200 herewith attached were satisfactory checked and signed.

The above is considered in accordance with the mentioned specifications requirements, therefore the subject valve has satisfactorily passed the prescribed fire test and can be also qualified as follows:

**NPS** 

**CLASS RATING** 

**MATERIALS** 

6" and larger

150# and 300#

Carbon steel, (see drawing)

BARCELONA REGISTER OF SHIPPER

J.Gil for II. Picazo Surveyors to Lloyd's Register

**DOCUMENTS ATTACHED:** 

